





Dear Valued Customer,

The pin orientation of Q1, the 2N3906 (221334) transistor, is incorrect on your LABC1 circuit board (Rev 1.2). Please insert Q1 (step 17) with the flat side (no writing) facing the front of the board towards the D5-D14 diode matrix. Have fun building and enjoy your LABC1!





The Staff at Ramsey Electronics



Dear Valued Customer,

The pin orientation of Q1, the 2N3906 (221334) transistor, is incorrect on your LABC1 circuit board (Rev 1.2). Please insert Q1 (step 17) with the flat side (no writing) facing the front of the board towards the D5-D14 diode matrix. Have fun building and enjoy your LABC1!

The Staff at Ramsey Electronics



Dear Valued Customer,

The pin orientation of Q1, the 2N3906 (221334) transistor, is incorrect on your LABC1 circuit board (Rev 1.2). Please insert Q1 (step 17) with the flat side (no writing) facing the front of the board towards the D5-D14 diode matrix. Have fun building and enjoy your LABC1!

The Staff at Ramsey Electronics

